



NO	Name	Amount
14	cable compaction handle	1
15	screw ST4x22-C-H	2
16	capacitance	1
17	check seep board	1
18	base	1
19	screw S15x16-C-H	3
20	nut M8	1
21	impeller	1
22	washer (ø8)	1
23	washer	1
24	immobility ring	1
25	screw M4x14	6
26	press ring	1
27	o-ring 90x5 G	1
28	ring B12x4x,5	3
29	motor foreside	1
30	motor lining (28±0.105)	1
31	bearing 201-2Z	2
32	rotor	1
33	undeel	1
34	stator	1
35	washer 4	1
36	screw S13.5x9.5-C-H	1
37	earthing line	1
38	back shell	1
39	washer 4	1
40	valve	1
41	steel ball (3.35 (1/4"))	1
42	o-ring 10.5x2 G	1
43	nut	1
44	o-ring 4.87x1.8 G	8
45	washer ø4.9	6
46	screw M5x12	5

Q1DS-400C, 550C, 750C, 900C, 1100C